

Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: Wiepking Fullerton Energy LLC- #96340

Location ID: 433577

Inspection Document #: 709400962

Lincoln County, CO

NESE Section 23 T10S R56W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Big Wanmum #1
Location ID: 433577



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing east of wellhead.



Inspection Photos
Location Name: Big Wanmum #1
Location ID: 433577



Photo 3. Photo taken facing east of stained soil around wellhead.



Photo 4. Photo taken facing east of secondary containment without wildlife protection.

Inspection Photos
Location Name: Big Wanmum #1
Location ID: 433577



Photo 5. Photo taken facing southeast of vegetation and weeds on well pad.



Photo 6. Photo taken facing northeast of vegetation in the interim reclamation area.

Inspection Photos
Location Name: Big Wanmum #1
Location ID: 433577



Photo 7. Photo taken facing northwest of vegetation and weeds (russian thistle and kochia) on the fill slope of well pad.



Photo 8. Photo taken facing west of vegetation and weeds (russian thistle and kochia) on the fill slope of well pad.

Inspection Photos

Location Name: Big Wanmum #1

Location ID: 433577



Photo 11. Photo taken facing east of tank battery sign



Photo 12. Photo taken facing east of tank battery.



Inspection Photos
Location Name: Big Wanmum #1
Location ID: 433577



Photo 11. Photo taken facing north of tank battery pad, vegetation in the interim reclamation area.



Photo 12. Photo taken facing west of tank battery pad, vegetation in the interim reclamation area.