

Interim Reclamation and Stormwater Inspection

March 12 , 2024

Operator: Citation Oil & Gas Corp.- #17180

Location ID: 324941

Inspection Document #: 709400974

Kit Carson County, CO

NESE Section 36 T11S R51W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Speaker State 43-36 #1
Location ID: 324941



Photo 1. Photo taken of location sign.



Photo 2. Photo taken facing west of injection well on site

Inspection Photos
Location Name: Speaker State 43-36 #1
Location ID: 324941



Photo 3. Photo taken facing south of anchor and mowed vegetation in interim reclamation area.



Photo 4. Photo taken facing east of down fencing remove or replace. .

Inspection Photos

Location Name: Speaker State 43-36 #1

Location ID: 324941



Photo 5. Photo taken facing east of down fencing remove or replace. .



Photo 6. Photo taken facing east ofterash (old wire) on site.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400974

Inspection Photos

Location Name: Speaker State 43-36 #1

Location ID: 324941



Photo 7. Photo taken facing east of stormwater erosion on access road leading from tank battery to well pad.



Photo 8. Photo taken facing east of stormwater erosion on access road leading from tank battery to well pad.

Inspection Photos

Location Name: Speaker State 43-36 #1

Location ID: 324941



Photo 9. Photo taken facing northwest of tank battery.



Photo 10. Photo taken facing northeast at tank battery pad of inadequate perimeter berm around tank battery. Yellow arrow indicates the berm.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400974

Inspection Photos

Location Name: Speaker State 43-36 #1

Location ID: 324941



Photo 11. Photo taken facing east of breached berm around tank battery, allowing stormwater and potential spills to leave containment.



Photo 12. Photo taken facing northwest at tank battery pad, of breached berm around sed onsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400974

Inspection Photos

Location Name: Speaker State 43-36 #1

Location ID: 324941



Photo 11. Photo taken facing south at tank battery pad of stained soil at entrance of shed on site.



Photo 12. Photo taken facing southwest at tank battery pad, of mowed vegetation in interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400974