

# Inspection Photos

API: 099-06881

Operator: STRACHAN EXPLORATION INC

Inspection Date: 3/15/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing northeast toward the wellsite location.



## Inspection Photos



**Photo 2.** Well sign is posted at meter shed.



## Inspection Photos



**Photo 3.** Facing north toward the open top tank. The tank is inside the bermed secondary containment.



## Inspection Photos



**Photo 4.** Facing toward the open top tank. There is no netting or labeling at the tank.



## Inspection Photos



**Photo 5.** There is no wildlife protection on the open top tank. Red arrows point to dead birds found in the tank.



## Inspection Photos



**Photo 6.** There were 4 dead birds pulled out of the tank.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 099-06881 | Date: 3/15/2024