

Inspection Photos
Location Name: Grant 1
Location ID: 333136



Photo 1 Location.



Photo 2 Ancillary equip.

Inspection Photos
Location Name: Grant 1
Location ID: 333136



Photo 3 Wellsite.



Photo 4 Pump jack.

Inspection Photos
Location Name: Grant 1
Location ID: 333136



Photo 5 Wellsite.



Photo 6 WH.

Inspection Photos
Location Name: Grant 1
Location ID: 333136



Photo 7 WH sign.



Photo 8 Electric panel, prime mover.