

Inspection Photos
Location Name: Thomas L Russell 'D'1
Location ID: 336222



Photo 1 Location.



Photo 2 Dead vegetation around the WH.

Inspection Photos
Location Name: Thomas L Russell 'D'1
Location ID: 336222



Photo 3 Dead vegetation(debris) inside of the wellsite fencing around the WH.

Photo 4 WH sign.

Inspection Photos
Location Name: Thomas L Russell 'D'1
Location ID: 336222



Photo 5 Ancillary Equip.



Photo 6 Pump jack.