

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 1 Location access road over run with dead vegetation(Debris).



Photo 2 Wellsite over run with dead vegetation(Debris).

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 3 WH sign.



Photo 4 Dead vegetation(debris) around the WH.

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 5 Ancillary Equip.



Photo 6 Dead vegetation & trash inside wellsite fencing.

Inspection Photos
Location Name: Guadagnoli 2
Location ID: 318225



Photo 7 Dead vegetation & trash inside wellsite fencing.



Photo 8 Dead vegetation & trash outside of wellsite fencing on location.