

Final Reclamation Inspection

March 19th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326098

Inspection Document #: 714000577

La Plata County, CO

Township: NENW 36 35N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State of Colorado 36-3
Location ID: 326098

3/19/24
+37.262406,-107.807071
310° NW



Photo 1. Overview of the disturbance taken from the entrance facing center.



API #: 067-07467

Inspection Photos

Location Name: State of Colorado 36-3

Location ID: 326098



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Trash corrective action identified in the previous inspection doc #714000051 has been addressed/resolved.

API #: 067-07467

Inspection Photos
Location Name: State of Colorado 36-3
Location ID: 326098

3/19/24
+37.262806,-107.807028
280° W



Photo 3. View of the northern interim reclamation area facing west.



Inspection Photos

Location Name: State of Colorado 36-3

Location ID: 326098



Photo 4. View of unused oil and gas equipment at the pump jack.



Inspection Photos

Location Name: State of Colorado 36-3

Location ID: 326098



3/19/24
+37.262443,-107.807565
187° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of Reference area comprised of smooth brome, sage brush and juniper.

API #: 067-07467