

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 9866 From entrance to location



Photo # 9867 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 9868 Location



Photo # 9869 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 9870 Location



Photo # 9871 Cellar cover not properly installed/wildlife & personnel hazard & wildlife egress not properly installed.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1802 from inspection 708900877 conducted on 06/26/2023 - Unused equipment/ECD disconnected



Photo # 9872 Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1803 from inspection 708900877 conducted on 06/26/2023 - Unused equipment/ECD disconnected



Photo # 9873 Unused equipment/ECD disconnected