

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad

Location ID: 335108



Photo # 771 From entrance to location




Photo # 772 Location

**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad**  
**Location ID: 335108**



### Photo # 773 Location



### Photo # 774 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad

Location ID: 335108



Photo # 775 Location



Photo # 776 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad

Location ID: 335108



Mar 20, 2024 at 1:45:04 PM  
CO

**Photo # 777 Location**



Mar 20, 2024 at 1:46:06 PM  
CO

**Photo # 778 Location**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad

Location ID: 335108



Photo # 779 Location



Photo # 780 Stained soils & gravel