

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad
Location ID: 335108



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 22 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad
Location ID: 335108



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad
Location ID: 335108



Photo # 781 Wattles need maintenance/stormwater undercutting BMP's & transporting sediment off location



Photo # 782 Wattles need maintenance/stormwater undercutting BMP's & transporting sediment off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 311-22 Pad
Location ID: 335108



Photo # 783 Wattles need maintenance/stormwater undercutting BMP's & transporting sediment off location



Photo # 784 Check dam needs maintenance/stormwater eroding around BMP & cutting into secondary containment berm