

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 312 From entrance to location



Photo # 313 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 314 Location




Photo # 315 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 316 Location



Photo # 317 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 318 Location



Photo # 319 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 320 Tank capacity incorrect



Photo # 321

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-W-29 Pad

Location ID: 335389



Photo # 322 Stained soils & gravel