

Inspection Photos
Location Name: Castor LC 34-68HN
Location ID: 422926



Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Castor LC 34-68HN
Location ID: 422926



Photo 3 – Tank Battery

Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Castor LC 34-68HN
Location ID: 422926



Energy and Carbon Management Commission
40.71297, -103.97061, 4786.6ft
03/19/2024 13:10:26



Energy and Carbon Management Commission
40.71263, -103.97042, 4799.1ft
03/19/2024 13:10:46

Photo 5 – Separators and ECD

Photo 6 – Compressor

Inspection Photos
Location Name: Castor LC 34-68HN
Location ID: 422926



Energy and Carbon Management Commission
40-7128, -103-97022, 4802.1ft
03/19/2024 13:11:00

Photo 7 – Gas Meters



Energy and Carbon Management Commission
40-71288, -103-9703, 4791.4ft
03/19/2024 13:11:10

Photo 8 – Compressor and VRU

Inspection Photos
Location Name: Castor LC 34-68HN
Location ID: 422926



Photo 9 – Tank Battery – Back Side