

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2024

Submitted Date:

03/25/2024

Document Number:

696306129

FIELD INSPECTION FORM

Loc ID 424891 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boyd, William		wboyd@pedevco.com	All Inspections
Shepard, DeAnn		dshepard@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424862	WELL	PR	01/01/2021	OW	123-34199	Hahn 1-4H	PR

General Comment:[This is a Well and Tank Battery Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Gas Engine, Exhaust and Wellhead ; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	04/08/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Other	# 2		

Comment:	Propane Tanks (500 Gallons)		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Flare	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Gas Engine		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.596780,-104.319280
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type	Field Flare				
Comment:					
Corrective Action:					Date:

