

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 323840



Photo # 1137 From entrance to location



Photo # 1138 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 323840



Photo # 1139 Location



Photo # 1140 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 323840



Mar 25, 2024 at 9:59:56 AM  
CO

Photo # 1141 Location



Mar 25, 2024 at 9:55:12 AM  
CO

Photo # 1142 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BENTON GV 15-36 Pad

Location ID: 323840



Photo # 1143 Netting/wildlife protection needs maintenance



Photo # 1144 Debris