

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 3/25/2024



Location Entrance – Photo #00044



Location Entrance – Photo #00045

Date: 3/25/2024



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 3/25/2024



Tank Battery – Photo #00048



Insufficient Erosion Control – Photo #00049

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/29SESE

Location ID: 324177

Date: 3/25/2024



Lack of Stabilization – Photo #00050



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00051**