

Final Reclamation Inspection

March 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326347

Inspection Document #: 714000603

La Plata County, CO

Township: NENW 27 35N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sauls Creek B 1
Location ID: 326347



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: Sauls Creek B 1
Location ID: 326347



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Northern interim reclamation area facing east. Vegetation comprised of intermediate wheatgrass, gambel oak and pine.

API #: 067-07887

Inspection Photos
Location Name: Sauls Creek B 1
Location ID: 326347



Photo 3. Impacted material observed at the well head.



Inspection Photos
Location Name: Sauls Creek B 1
Location ID: 326347



Photo 4. Unused oil and gas fitting equipment observed at the pump jack.



Inspection Photos
Location Name: Sauls Creek B 1
Location ID: 326347



3/22/24
+37-276321,-107.518936
162° S

Photo 5. Reference comprised of smooth brome, gambel oak and pine.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources