

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 1 Location.



Photo 2 Wellsite.

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 3 Dead vegetation(Debris) around the WH.



Photo 4 WH sign.

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 5 Dead vegetation(Debris) around the ancillary equipment.



Photo 6 Dead vegetation(Debris) around the Wellsite.

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 7 Dead vegetation(Debris) around the wellsite/disassembled PJ.



Photo 8 Dead vegetation(Debris) around the Wellsite/disassembled PJ.

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 9 Dead vegetation(Debris) around the ancillary equip.



Photo 10 Dead vegetation(Debris) around the Wellsite.

Inspection Photos
Location Name: Nesssu-Kinder 16
Location ID: 331124



Photo 11 Dead vegetation(Debris) around the WH.



Photo 12 Dead vegetation(Debris) around the PJ base.