

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Mar 26, 2024 at 12:05:23 PM
CO



Mar 26, 2024 at 12:08:04 PM
CO

Photo # 1524 From entrance to location

Photo # 1525 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Photo # 1526 Location



Photo # 1527 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad
Location ID: 311547



Photo # 1528 Location



Photo # 1529 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Photo # 1530 Location



Photo # 1531 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Photo # 1532 Uncovered cellar/available for entry by wildlife/wildlife hazard



Photo # 1533 Uncovered cellar/available for entry by wildlife/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Photo # 1534 KNIGHT W-6-4 bradenhead tied into flowline/No Form 4 Sundry



Photo # 1535 KNIGHT W-6-4 bradenhead tied into flowline/No Form 4 Sundry

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT W-6-4 Pad

Location ID: 311547



Photo # 1536 KNIGHT W-6-4 bradenhead tied into flowline/No Form 4 Sundry



Photo # 1537 Debris