

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2024

Submitted Date:

03/28/2024

Document Number:

710100127

FIELD INSPECTION FORM

 Loc ID: 406152
 Inspector Name: Anderson, Laurel
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 93200

Name of Operator: VESSELS OIL & GAS COMPANY

Address: 8435 W 88TH AVE

City: ARVADA State: CO Zip: 80005

Contact Information:

Contact Name	Phone	Email	Comment
HARTFIELD, RICHARD	303-421-9379	rhartfield@hjstax.com	GENERAL COUNSEL

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239994	WELL	PA	06/15/1983	GW	123-07782	SACK-HIETT 1	PA
485295	SPILL OR RELEASE	AC	11/02/2023		-	Sack-Hiett #1	EI

General Comment:

This is an environmental inspection of the Sack-Hiett #1 well (API 05-123-07782) and Spill/Release Point ID #485295.

On October 17, 2023, Verdad Resources LLC (Operator #10651) submitted an Initial Form 19 Spill/Release Report (document no. 403563609) due to a suspected historical release (visibly impacted soil) discovered on October 16th, 2023, when the historically plugged and abandoned Sack-Hiett 1 well (API 05-123-07782) well owned by Vessels Oil & Gas Company (Operator #93200) was being exposed in preparation for offset abandoned well re-entry required by Rule.

On October 26, 2023, Verdad Resources LLC (Operator #10651) submitted an Supplemental Form 19 Spill/Release Report (document no. 403574055) including photo documentation (Doc #403574068 & Doc #403574069) of the visibly impacted soil within the open excavation around the former well.

The excavation was backfilled at the time of this inspection. Photos attached document site conditions at the time of inspection.

Inspected Facilities

Facility ID: 239994 Type: WELL API Number: 123-07782 Status: PA Insp. Status: PA

Facility ID: 485295 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: On October 17, 2023, Verdad Resources LLC (Operator #10651) submitted an Initial Form 19 Spill/Release Report (document no. 403563609) due to a suspected historical release (visibly impacted soil) discovered on October 16th, 2023, when the historically plugged and abandoned Sack-Hiett 1 well (API 05-123-07782) well owned by Vessels Oil & Gas Company (Operator #93200) was being exposed in preparation for offset abandoned well re-entry required by Rule.

Corrective Action: Pursuant to Rule 913.c.(8), ECMC is requesting Vessels Oil & Gas Company ("Operator") prepare and obtain the Director's approval of a Form 27 Site Investigation and Remediation Workplan to investigate potential impacts to soil and groundwater at the Sack-Hiett 1 well by March 14, 2024. Date: 03/29/2024

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710100128	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6484894