

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1260 From entrance to location



Photo # 1261 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1262 Location



Photo # 1263 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1264 Location




Photo # 1265 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1266 Location



Photo # 1267 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1268 Hose on pump open ended/wildlife hazard



Photo # 1269 Improperly marked deadman

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad

Location # 334873



Photo # 1270 Improperly marked deadman