

Inspected Facilities

Facility ID: 299967 Type: WELL API Number: 123-29579 Status: TA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: ECMC Environmental Inspection Remediation Project 29700 for well plugging, cut & cap and Rule 911 assessment. ECMC notes cut and cap date of 2/29/2024 on pending Form 6-S. Site is backfilled. ECMC expects Supplemental Form 27 by May 29, 2024 (90 days after cut and cap date).

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):