

# Final Reclamation Inspection

March 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307019

Inspection Document #: 714000614

La Plata County, CO

Township: NESW 25 33N 11W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019

3/28/24  
+36.845716,-107.971055  
22° N



**Photo 1.** Overview of the disturbance taken from the southern edge facing center.



Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019



3/28/24  
+36.845716,-107.971055  
29° NE

**Photo 2.** View of the well head marker facing north.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09567

Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019




**Photo 3.** Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019



**Photo 4.** Cardinal photos taken from the center of the disturbance. Left photo facing south and right photo facing west. Note: project area vegetation and density appears consistent with adjacent reference area

Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019



**Photo 5.** Perimeter fence remains on location. Fence will need to be removed before location can pass final reclamation.



Inspection Photos  
Location Name: Eldridge 25-02 2  
Location ID: 307019

3/28/24  
+37.074737,-107.995172  
9° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference comprised of sagebrush, rabbit brush, grease wood, smooth brome and crested wheatgrass.

API #: 067-09567