

Final Reclamation Inspection

March 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 307018

Inspection Document #: 714000615

La Plata County, CO

Township: NWNE 25 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eldridge 25-01 2
Location ID: 307018

3/28/24
+37.074778,-107.995192
71° E



Photo 1. Overview of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Eldridge 25-01 2
Location ID: 307018

3/28/24
+37.081752,-107.990575
215° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the southern interim reclamation area facing south.
Vegetation comprised of crested wheatgrass and rabbitbrush.

API #: 067-09566

Inspection Photos
Location Name: Eldridge 25-01 2
Location ID: 307018



Photo 3. Both produced water signs/placards on location are deteriorating and no longer displaying tank capacity.

Inspection Photos
Location Name: Eldridge 25-01 2
Location ID: 307018

3/28/24
+37.081675,-107.990804
216° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Corrective action for weeds at the access road identified in the previous inspection doc #693903414 has been addressed/resolved.

API #: 067-09566

Inspection Photos
Location Name: Eldridge 25-01 2
Location ID: 307018



3/28/24
+37.082272,-107.990413
318° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference are comprised of sagebrush, juniper and crested wheatgrass.

API #: 067-09566