

# Final Reclamation Inspection

March 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325188

Inspection Document #: 714000617

La Plata County, CO

Township: NWSE 25 33N 11W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ada EPA 1  
Location ID: 325188

3/28/24  
+37.073348,-107.990446  
132° SE



Photo 1. Overview of the disturbance taken from the access point facing center.



3/28/24  
+37.050291,-107.989003  
126° SE



Inspection Photos  
Location Name: Ada EPA 1  
Location ID: 325188



3/28/24  
+37.073348,-107.990446  
276° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the western interim reclamation area facing west.  
Vegetation comprised of rabbitbrush and crested wheatgrass.

API #: 067-05577



Inspection Photos  
Location Name: Ada EPA 1  
Location ID: 325188



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Large 10 x 15 ft. unused empty shed observed stored on location.

API #: 067-05577



3/28/24  
+37.072848,-107.990103  
203° SW



**Photo 4.** Gully erosion forming in the southern portion of the disturbance.



Inspection Photos  
Location Name: Ada EPA 1  
Location ID: 325188

3/28/24  
+37.072676,-107.990017  
160° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of sagebrush, crested wheatgrass and grease wood.

API #: 067-05577