

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2024

Submitted Date:

04/01/2024

Document Number:

709100254**FIELD INSPECTION FORM**Loc ID 317259 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 1165 DELAWARE STREET #200City: DENVER State: CO Zip: 80204**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Kilian Collins		kilian.collins@state.co.us	
Arthur Koepsell		arthur.koepsell@state.co.us	
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102662	PIT	AC			-	VANITA FRENCH 1	EI

General Comment:

On March 27, 2024, ECMC Environmental Unit Staff Krystal Heibel and Abdul Elnajdi inspected the Vanita French pit (Facility ID: 102662).

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	COGIS lists that pits are on location; while no Form 27 Decommissioning Plan has been received.		
Corrective Action:	Operator shall submit a Site Investigation and Remediation Workplan (Form 27), which will include a sampling plan, decommissioning plan, and a plan to remove unused equipment, reclaim the location, and remove undesirable vegetation. Operator shall comply with Rule 1004.a.. "Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well."		Date: <u>05/02/2024</u>
Type:	#		
Comment:	Pit not at location listed in COGIS		
Corrective Action:	Operator shall provide an updated Form 15: Pit Report/Permit updating the pit coordinates. It appears that the Latitude and Longitude coordinates for the pit are incorrect. Operator shall submit the Form 27 with accurate coordinates for the pit.		Date: <u>05/02/2024</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	102662	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100255	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6489759