

Inspection Photos
Location Name: Margaret Twombly B 5
Location ID: 318922



Energy & Carbon Management Commission
48-15076, -104.78448, 4846.3ft, 333°
04/01/2024 15:56:21



Energy & Carbon Management Commission
48-15085, -104.78452, 4851.0ft, 345°
04/01/2024 15:56:34

Photo 1 Location.

Photo 2 WH.

Inspection Photos
Location Name: Margaret Twombly B 5
Location ID: 318922



Photo 3 Faded WH sign.

Photo 4 Ancillary Equip.

Inspection Photos
Location Name: Margaret Twombly B 5
Location ID: 318922



Photo 5 Pump Jack.