

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: BEEBE DRAEW-64N65W 26SWSW

Loc ID: 319335

Inspection: 714200777



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Unused equipment on various areas of location. See attached photos. Comply with Rule 606.

CA Resolution: Operator has removed the unused equipment from the location to comply with Rule 606.

CA: Stained soil at wellhead and surrounding area. See attached photos. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.

CA Resolution: Operator addressed and appropriately removed identified stained soil. Equipment has been reviewed to help address/prevent leaks.