

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2024

Submitted Date:

03/26/2024

Document Number:

696306143**FIELD INSPECTION FORM**Loc ID 435720 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment |
|--------------|-------|---|---------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com |         |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name                    | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|----------------------------------|-------------|
| 435720      | LOCATION | AC     |             |            | -         | BULLEIT FEDERAL PC LG<br>04-62HN | AC          |
| 435721      | WELL     | PR     | 08/01/2023  | OW         | 123-38758 | BULLEIT FEDERAL PC LG<br>04-62HN | PR          |

**General Comment:**[This is a Well and Tank Battery Inspection](#)

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | Stained Soil at Compressor; see photos   |       |            |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." | Date: | 04/15/2024 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Panels      |       |  |
| Corrective Action: |             | Date: |  |
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |

|                     |     |       |                 |
|---------------------|-----|-------|-----------------|
| <b>Equipment:</b>   |     |       | corrective date |
| Type: Gas Meter Run | # 3 |       |                 |
| Comment:            |     |       |                 |
| Corrective Action:  |     | Date: |                 |

|                                   |                                  |       |
|-----------------------------------|----------------------------------|-------|
| Type: Bradenhead                  | # 1                              |       |
| Comment:                          | Appears to be plumbed to surface |       |
| Corrective Action:                |                                  | Date: |
| Type: Plunger Lift                | # 1                              |       |
| Comment:                          |                                  |       |
| Corrective Action:                |                                  | Date: |
| Type: Emission Control Device     | # 3                              |       |
| Comment:                          |                                  |       |
| Corrective Action:                |                                  | Date: |
| Type: VRU                         | # 1                              |       |
| Comment:                          |                                  |       |
| Corrective Action:                |                                  | Date: |
| Type: Horizontal Heated Separator | # 2                              |       |
| Comment:                          |                                  |       |
| Corrective Action:                |                                  | Date: |
| Type: Compressor                  | # 1                              |       |
| Comment:                          |                                  |       |
| Corrective Action:                |                                  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 300 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type         | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | PBV CONCRETE |         | ,      |
| Comment:           |   |          |              |         |        |
| Corrective Action: |   |          |              |         | Date:  |

**Paint**

|                 |  |  |
|-----------------|--|--|
| Condition       |  |  |
| Other (Content) |  |  |

|   |          |          |                     |  |                     |                       |
|---|----------|----------|---------------------|--|---------------------|-----------------------|
| Other (Capacity) 60 BBLs                      |          |          |                     |  |                     |                       |
| Other (Type)                                  |          |          |                     |  |                     |                       |
| <b>Berms</b>                                  |          |          |                     |  |                     |                       |
| Type  | Capacity |          | Permeability (Wall) |  | Permeability (Base) | Maintenance           |
|   |          |          |                     |  |                     |                       |
| Comment: Shares berm with the Crude Oil Tanks |          |          |                     |  |                     |                       |
| Corrective Action:                            |          |          |                     |  |                     | Date:                 |
| Contents                                      | #        | Capacity | Type                |  | Tank ID             | SE GPS                |
| CRUDE OIL                                     | 5        | 300 BBLs | STEEL AST           |  |                     | 40.684440,-103.972070 |
| Comment:                                      |          |          |                     |  |                     |                       |
| Corrective Action:                            |          |          |                     |  |                     | Date:                 |
| <b>Paint</b>                                  |          |          |                     |  |                     |                       |
| Condition                                     | Adequate |          |                     |  |                     |                       |
| Other (Content)                               |          |          |                     |  |                     |                       |
| Other (Capacity)                              |          |          |                     |  |                     |                       |
| Other (Type)                                  |          |          |                     |  |                     |                       |
| <b>Berms</b>                                  |          |          |                     |  |                     |                       |
| Type  | Capacity |          | Permeability (Wall) |  | Permeability (Base) | Maintenance           |
| Metal   | Adequate |          | Walls Sufficient    |  | Base Sufficient     | Adequate              |
| Comment:                                      |          |          |                     |  |                     |                       |
| Corrective Action:                            |          |          |                     |  |                     | Date:                 |
| <b>Venting:</b>                               |          |          |                     |  |                     |                       |
| Yes/No  | NO       |          |                     |  |                     |                       |
| Comment:                                      |          |          |                     |  |                     |                       |
| Corrective Action:                            |          |          |                     |  |                     | Date:                 |
| <b>Flaring:</b>                               |          |          |                     |  |                     |                       |
| Type  |          |          |                     |  |                     |                       |
| Comment:                                      |          |          |                     |  |                     |                       |
| Corrective Action:                            |          |          |                     |  |                     | Date:                 |

