

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 1 Location over run with dead vegetation inside the dead man anchors.

Photo 2 Dead vegetation around unused pump jack base.

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 3 Wellsite.

Photo 4 WH sign.

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 5 WH.

Photo 6 Unused meter box & electric panel.

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 7 Dead vegetation around unused pump jack parts inside the dead man anchors .

Photo 8 Dead vegetation around unused pump jack parts inside the dead man anchors.

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 9 Dead vegetation around unused pump jack parts inside the dead man anchors .

Photo 10 Dead vegetation inside the dead man anchors.

Inspection Photos
Location Name: Vonasek 5
Location ID: 311316



Photo 11 Dead vegetation around unused pump jack parts inside the dead man anchors .