

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



As signs are replaced additional information is required

Access road to location

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



Wellhead signs missing required information



Replace labels when no longer legible.

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



Unmarked anchor



Debris or Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



Unmarked anchor



Soil staining

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



Location from Southwest corner



Location from Southeast corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NWNW
Location ID: 398836



Location from Northeast corner

Location from Northwest corner