


Inspection Photos

Location Name: Bath-Schmier 5N64W32 1-11 Tank Battery

Location ID: 451280



Location Sign



Inspection Photos

Location Name: Bath-Schmier 5N64W32 1-11 Tank Battery

Location ID: 451280



Location



Production Equipment


Inspection Photos

Location Name: Bath-Schmier 5N64W32 1-11 Tank Battery

Location ID: 451280



ECDs




Production Tanks

Inspection Photos
Location Name: Bath-Schmier 5N64W32 1-11 Tank Battery
Location ID: 451280




Lact, Bulk separator, & Air compressor



Stained Soil

Inspection Photos
Location Name: Bath-Schmier 5N64W32 1-11 Tank Battery
Location ID: 451280



Unmarked Riser



Unmarked Riser