

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Erosion and sediment migration




Erosion and sediment migration

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



No visible display of gas meter calibration



Gas meter calibration out of date

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Sediment migration and vehicle tracking



Erosion and sediment migration.

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



When replaced additional information is required



When replaced additional information is required

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Weeds from last summer



Last summer weed growth

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393




Unused equipment



Debris

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Open to wildlife



Staining

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393




Illegible label. Tank overflow.



Unused equipment.

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Staining




Illegible label

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Soil staining



Soil staining

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Debris



Stained soil

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Debris



Vehicle tracking

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Vehicle tracking



Unused equipment. Tank is empty.

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Oil spray from tank berm



Metal berm seeping.

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Metal berm seepage.



Metal berm seepage.

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Metal berm seepage.



Metal berm seepage.

**KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393**



Sediment migration. Vehicle tracking.



Sediment migration. Vehicle tracking.

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Location from Southwest corner



Location from Southeast corner

KT Resources LLC
WRD Unit-62S97W 25SESE
Location ID: 336393



Location from Northeast corner



Location from Northwest corner