

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 1947 From entrance to location



Photo # 1948 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Apr 1, 2024 at 11:02:49 AM
CO



Apr 1, 2024 at 11:06:56 AM
CO

Photo # 1949 Location

Photo # 1950 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 1951 Location



Photo # 1952 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 1953 Location



Photo # 1954 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9412 From inspection 708902524 conducted on 12/11/2023 Stored vehicles & trailers on location



Photo # 1955 Stored vehicles & trailers on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9413 From inspection 708902524 conducted on 12/11/2023 Stored vehicles, trailers & miscellaneous equipment on location



Photo # 1956 Stored vehicles, trailers & miscellaneous equipment on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 9414 From inspection 708902524 conducted on 12/11/2023 Stored vehicles on location



Photo # 1957 Stored vehicles on location

Inspection Photos

Location Name: TEP Rocky Mountain LLC OVERACKER 29-04 Pad

Location # 311653



Photo # 1958 Stored vehicles, trailers & miscellaneous equipment



Photo # 1959 Stored vehicles on location