

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2024

Submitted Date:

03/28/2024

Document Number:

710100127

FIELD INSPECTION FORMLoc ID 406152 Inspector Name: Anderson, Laurel On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 93200

Name of Operator: VESSELS OIL & GAS COMPANY

Address: 8435 W 88TH AVE

City: ARVADA State: CO Zip: 80005

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARTFIELD, RICHARD	303-421-9379	rhartfield@hjstax.com	GENERAL COUNSEL

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239994	WELL	PA	06/15/1983	GW	123-07782	SACK-HIETT 1	PA
485295	SPILL OR RELEASE	AC	11/02/2023		-	Sack-Hiett #1	EI

General Comment:

This is an environmental inspection of the Sack-Hiett #1 well (API 05-123-07782) and Spill/Release Point ID #485295.

On October 17, 2023, Verdad Resources LLC (Operator #10651) submitted an Initial Form 19 Spill/Release Report (document no. 403563609) due to a suspected historical release (visibly impacted soil) discovered on October 16th, 2023, when the historically plugged and abandoned Sack-Hiett 1 well (API 05-123-07782) well owned by Vessels Oil & Gas Company (Operator #93200) was being exposed in preparation for offset abandoned well re-entry required by Rule.

On October 26, 2023, Verdad Resources LLC (Operator #10651) submitted an Supplemental Form 19 Spill/Release Report (document no. 403574055) including photo documentation (Doc #403574068 & Doc #403574069) of the visibly impacted soil within the open excavation around the former well.

The excavation was backfilled at the time of this inspection. Photos attached document site conditions at the time of inspection.

Inspected Facilities									
Facility ID:	239994	Type:	WELL	API Number:	123-07782	Status:	PA	Insp. Status:	PA
Facility ID:	485295	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

On October 17, 2023, Verdad Resources LLC (Operator #10651) submitted an Initial Form 19 Spill/Release Report (document no. 403563609) due to a suspected historical release (visibly impacted soil) discovered on October 16th, 2023, when the historically plugged and abandoned Sack-Hiett 1 well (API 05-123-07782) well owned by Vessels Oil & Gas Company (Operator #93200) was being exposed in preparation for offset abandoned well re-entry required by Rule.

Corrective Action:

Pursuant to Rule 913.c.(8)., ECMC is requesting Vessels Oil & Gas Company ("Operator") prepare and obtain the Director's approval of a Form 27 Site Investigation and Remediation Workplan to investigate potential impacts to soil and groundwater at the Sack-Hiett 1 well by March 14, 2024.

Date:

03/29/2024

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403734492	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6484898
710100128	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6484894