

Inspection Photos

API: 071-06516

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main access road. The cattle guard has filled in with sediment and needs to be cleaned out.



Inspection Photos



Photo 2. There are two additional cattleguards further along the road that have filled in with sediment.



Inspection Photos



Photo 3. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing north at the location. There are two dumpsters at the location which should be placed off location to keep unauthorized use of the wellsite for safety.



Inspection Photos



Photo 5. Facing toward the wellhead.



Inspection Photos



Photo 6. There is unused pipe, shed, and frac tank that needs to be removed..

