

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 4/4/2024



Apr 4, 2024 at 11:22:10



Apr 4, 2024 at 11:22:30
De Beque CO 81630
United States

Location Entrance – Photo #00390


Wellheads – Photo #00391

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 4/4/2024



Separators – Photo #00393



Tank Battery – Photo #00395

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 4/4/2024



Lack of Stabilization – Photo #00396



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #00397