

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 4/4/2024



Location Entrance – Photo #00399



Wellhead – Photo #00400



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 4/4/2024



Separator/Dehydrator – Photo #00402



Tank Battery – Photo #00401



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4SWSW

Location ID: 324072

Date: 4/4/2024



**Lack of Stabilization – Photo #00403**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #00404**