

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 4/4/2024



Location Entrance – Photo #00418



Wellheads – Photo #00424




## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 4/4/2024



Separator/Dehydrator – Photo #00420



Tank Battery – Photo #00419



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 4/4/2024



Unprotected Soil Stockpile – Photo #00422



Unprotected Soil Stockpile – Photo #00423