

Inspection Photos
Location Name: Root Trust 18-16G
Location ID: 327585



Photo 1: Wellhead, no signage, damaged fencing.



Photo 2: Fencing damaged

Inspection Photos
Location Name: Root Trust 18-16G
Location ID: 327585



Photo 3: Tank Battery Sign



Photo 4: Tank Battery

Inspection Photos
Location Name: Root Trust 18-16G
Location ID: 327585



Photo 5: Equipment

