

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



**Photo 1 – Compressor**



**Photo 2 – 2-Stage Knock-Out Equipment**

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**




**Photo 3 – Instrumental Air Unit**

**Photo 4 – Gas Meters**

Inspection Photos  
Location Name: Timbro LC13 ECONODE  
Location ID: 431371



**Photo 5 – Separators**



**Photo 6 – Maintenance Tank – Content and Capacity Labels are missing**

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



**Photo 7 – VRTs and Heater Treater**

**Photo 8 – VRU**

Inspection Photos  
Location Name: Timbro LC13 ECONODE  
Location ID: 431371



Photo 9 – ECDs



Photo 10 – ECDs

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



**Photo 11 – Tank Battery**



**Photo 12 – Crude Oil Tanks**

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



**Photo 13 – Water Tanks**



**Photo 14 – Separators**

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



Energy and Carbon Management Commission  
40.74263, -103.92615, 4809.6ft  
04/03/2024 13:28:27

**Photo 15 – Unmarked Risers at Separators**



Energy and Carbon Management Commission  
40.7424, -103.92569, 4792.2ft  
04/03/2024 13:29:11

**Photo 16 – Gas Meters**

**Inspection Photos**  
**Location Name: Timbro LC13 ECONODE**  
**Location ID: 431371**



**Photo 17 – Instrumental Air Unit**



**Photo 18 – Compressor**