

Final Reclamation Inspection

April 3rd, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 325128

Inspection Document #: 714000628

La Plata County, CO

Township: CNW 19 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mcelvain DKTA Unit 1
Location ID: 325128



Photo 1. Overview of the disturbance taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05373

Inspection Photos
Location Name: Mcelvain DKTA Unit 1
Location ID: 325128



Photo 2. Weedy russian thistle debris observed in the southern and northern portions of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05373

Inspection Photos
Location Name: Mcelvain DKTA Unit 1
Location ID: 325128



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the southern interim reclamation area comprised of smooth brome, intermediate wheatgrass and rabbitbrush.

API #: 067-05373

Inspection Photos
Location Name: Mcelvain DKTA Unit 1
Location ID: 325128

4/3/24
+37.092813,-107.763765
331° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of smooth brome, sagebrush and rabbitbrush.

API #: 067-05373