

# Final Reclamation Inspection

April 3rd, 2024

Operator: Advance Wireless Communications LLC  
- 10736

Location ID: 306981

Inspection Document #: 714000634

La Plata County, CO

Township: NWSE 18 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981

4/3/24  
+37.101404,-107.756473  
333° NW



Photo 1. Overview of the well pad disturbance the access point facing center.



Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981

4/3/24  
+37.101718,-107.756259  
318° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the northern interim reclamation area facing north west.  
Vegetation comprised of crested wheatgrass, western wheatgrass and  
rabbitbrush.

API #: 067-09317, 09752



Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981



**Photo 3.** View of stained material at both pump jack mufflers.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09317, 09752



Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981



4/3/24  
+37.101354,-107.756368  
191° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Wood pallet debris observed stored within the produced water tank berm.

API #: 067-09317, 09752



Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981

4/3/24  
+37.101196,-107.756258  
236° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Berm corrective action identified in the previous inspection doc #693903525 has been addressed/resolved.

API #: 067-09317, 09752



Inspection Photos  
Location Name: Slugger 2, 22  
Location ID: 306981

4/3/24  
+37.101812,-107.757072  
211° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of reference area comprised of tumble mustard and sagebrush.

API #: 067-09317, 09752