

Final Reclamation Inspection

April 3rd, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 325139

Inspection Document #: 714000635

La Plata County, CO

Township: NESE 18 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Helton MVRD GU 1
Location ID: 325139



Photo 1. Overview of the well pad disturbance the access point facing center.

Inspection Photos
Location Name: Helton MVRD GU 1
Location ID: 325139




Photo 2. View of russian thistle debris dominating the eastern portion of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05412

Inspection Photos
Location Name: Helton MVRD GU 1
Location ID: 325139



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of stormwater BMPs installed in the western cut slope/interim reclamation area.

API #: 067-05412

Inspection Photos
Location Name: Helton MVRD GU 1
Location ID: 325139

4/3/24
+37.101506,-107.753447
46° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the reference area comprised of western wheatgrass, sagebrush and juniper.

API #: 067-05412