

# Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 2989 From entrance to location




Photo # 2990 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 2991 Location



Photo # 2992 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 2993 Location



Photo # 2994 Open ended pipping on separator unit/wildlife hazard/available for entry by wildlife

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



**Photo # 2995 Open ended pipping on separator unit/wildlife hazard/available for entry by wildlife**