

Final Reclamation Inspection

April 4, 2024

Operator: HIGHPOINT OPERATING CORPORATION - #10071

Location ID: 420523

Inspection Document #: 697505252

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Critter Creek 24-30H
Location ID: 420523



Photo 1. Google Earth aerial imagery from 9/3/2023 illustrating the location. Operator has performed final reclamation activities; however, Operator has left an approximate 100' section of access road in-place.

Inspection Photos
Location Name: Critter Creek 24-30H
Location ID: 420523



Photo 2. Photo taken from the entrance of location off CR124, facing North. Operator has failed to remove gravel, recontour and reclaim an approximate 100' section of access road.



Photo 3. Photo taken from a section of the access road, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Critter Creek 24-30H
Location ID: 420523



Photo 4. Photo taken from the southern location, facing South. Photo illustrates unmanaged weeds.



Photo 5. Photo taken from the southern location, facing West. See comments under Photo 4.

Note- much of the location does have desirable plant establishment but there are patches of unmanaged weeds.

Inspection Photos
Location Name: Critter Creek 24-30H
Location ID: 420523



Photo 6. Photo taken from the southwestern location, facing North. Photo illustrates unmanaged weeds.

