

Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311904

Inspection Document #: 714000653

La Plata County, CO

Township: CNE 18 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: VD Helton
Location ID: 311904

4/5/24
+37.108074,-107.754233
174° S



Photo 1. Overview of the well pad disturbance from the access point facing center. Note: Wells share a disturbance with the Advanced Wireless Communications Slugger 1, 11 wells.

Inspection Photos
Location Name: VD Helton
Location ID: 311904



Photo 2. View of rutting/storm water issues observed on location.
Additional stabilization is needed to minimize site degradation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05749, 08175