

Environmental Inspection

April 10, 2024

Operator: Kerr McGee- #47120

Facility ID: 149021; Drill Fluids Management Facility #1

Inspection Document #: 712100002

Weld, CO

SW Section 34 T3N R66W

Alex Fischer

Environmental Supervisor - Western

Colorado, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 1. Entrance signage.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 2. Looking west from entrance into Facility.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 3. Looking northwest from entrance into Facility.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 5. Trash near trash containers and shed.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 6. Unused equipment near trash containers and shed.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 7. Crop emerging. Note: Trash in foreground.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 8. Soil conditions, sand with gravel.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Number: 712100002

Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 9. Cobble.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 10. Crop emerging.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 11. API 123-18248; SI and LOTO.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 12. Looking east along northern boundary of Facility. Wildlife and tall vegetation.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 13. Trash.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Number: 712100002

Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 14. Trash.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 15. Looking west along north boundary of Facility..



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 16. Looking south along east boundary of Facility..



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 17. API 123-19917; SI and LOTO.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 18. Concrete debris.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 19. Animal burrows.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 20. Animal burrows.



Inspection Photos

Facility Name: Drill Fluids Management Facility #1

Facility ID: 149021

Date: April 10, 2024



Photo 20. Trash/Debris.

