

Inspection Photos

04/04/2023

Operator: LARAMIE ENERGY LLC 10433

Location ID: 312618

Inspection Doc: 696205738

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312618



Photo 1: Photos 1-2 taken from the Location. Photos provide an overview of the Location from north, east, south to west. Final reclamation “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312618



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC 10433

Location ID: 312618



Photo 3: Location entrance, signage.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources