

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 1 Location.



Photo 2 WH.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 3 WH sign.



Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 5 Pump jack.



Photo 6 tank.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 7 Horizontal Heated Separator.



Photo 8 ECD.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710




Photo 9 Flow line manifold.



Photo 10 TB sign.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 11 TB.



Photo 12 Capped flow line needs retagged.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 13 Flow line needs to be retagged.



Photo 14 Stained soil at the base of the crude tank where it is rusted & pitted.

Inspection Photos
Location Name: Wooley 1
Location ID: 317710



Photo 15 Stained soil by a capped leaking valve on the crude tank.