

Inspection Photos

API: 061-06166

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 4/10/2024



Inspection Photos



Photo 1. Facing west at the wellsite location.



Inspection Photos



Photo 2. Facing northwest toward the location. There are unused areas of the location that must be reclaimed. Previous corrective action has not been completed.



Inspection Photos



Photo 3. Facing northwest toward the tank battery.



Inspection Photos



Photo 4. Facing northeast toward the location. There are unused areas of the location that must be reclaimed. Previous corrective action has not been completed.



Inspection Photos



Photo 5. Facing toward the TA'd well.

